

36TH INTERNATIONAL CONFERENCE ON COASTAL ENGINEERING 2018

Baltimore, Maryland | July 30 – August 3, 2018

The State of the Art and Science of Coastal Engineering

VIOLENT IN-CHAMBER LOADS IN AN OSCILLATING WATER COLUMN

Krisna Adi Pawitan, Ben Gossling, William Allsop, Tom Bruce



THE UNIVERSITY of EDINBURGH School of Engineering




Institute for Energy Systems

William Allsop Consulting Ltd



Oscillating Water Column mechanism



Source: Aqua-RET (aquaret.com)



Background problem

• Wave loading uncertainty inside the chamber







Damaged Mutriku wave power plant during construction due to storm Image: courtesy of Ezter Horvarth





Fig. 14. Impact of breaker on back wall.

Taken from:

Müller, G. and Whittaker, T.J., 1995. Visualisation of flow conditions inside a shoreline wave power-station. *Ocean engineering*, 22(6), pp.629-641.



Research aims:

• Observation and quantification In-chamber water column behaviour and wave loading characterisation , including impact/slam

Overview






THE UNIVERSITY of EDINBURGH School of Engineering




How?

physical model testing in Large wave flume (GWK) Hannover, Germany.



	Regular wave condition	Irregular wave condition
Wave height [m]	0.1 ≤ H ≤ 1.33	$0.26 \leq H_{mo} \leq 1.00$
Wave period [s]	3 ≤ T ≤ 6	$3 \le T_p \le 6.5$
Relative orifice opening (A _o /A _c)	0% - 2%	0% - 2%










Sloshing: non-uniform water column movement



Well behaved OWC

Sloshing

characterisatior

ethod





Column behaviour regime for Regular wave

Properties:

- / = not tested
- <u>i</u> = ceiling impact
- • = water column oscillation reached the ceiling

		Orifice Diameter in m (A _o /A _c)					
Bc/L	H (m)	Closed	0.06%	0.22%	1.00%	1.0% (lowered curtain wall)	2.00%
	0.1	/		/		/	
	0.15	/	/	/	/	/	
	0.2	/		/	/	/	
0.1394	0.26						
0.1394	0.39	/		/	/	/	/
	0.52						
	0.65	/		/		/	/
	0.78						<u>!</u>
	0.1	/		/	/	/	
	0.15	/	/	/	/	/	
0.1045	0.2	/		/		/	
	0.4						
	0.6	/		/		/	/
	0.8				<u>!</u>		
	1	/	/	/	<u>!</u>	/	/
	1.2	/	/	/	/	/	
0.0836	0.54				!		!
	0.81	/			1	/	/
	1.07	/	/	/	1	!	
	1.61	/	/	/	/	/	
	0.1	/		/	/	/	
0.0697	0.15	/	/	/	/	/	
	0.2	/		/	/	/	
	0.34						
	0.67						٨
	1	/	/	/	!	/	/
	1.33	/	/	/	/	/	



Column behaviour regime for Irregular wave

Properties:

ethod

- / = not tested
- <u>i</u> = ceiling impact

characterisation


 • = water column oscillation reached the ceiling

		Orifice Diameter in m (A _o /A _c)					
Bc/L	Hm0 (m)	Closed	0.06%	0.22%	1.00%	1.00% (lowered curtain wall)	2.00%
0.1394	0.26						
	0.39	/	/	/		/	/
	0.52		/	/			/
0.1045	0.4	/				/	<u>!</u>
	0.6		/	/			/
	0.8	/	/	/	!	/	/
0.0929	0.26		/	/		/	/
0.0836	0.54				!		ļ.
	0.81	/	/	/	!	/	/
0.0697	0.67		/	/	/		!
	1	/	/	/	!	/	/
0.0643	0.4	/	/	/		/	/







✤ Single impact on the front or rear of the chamber's ceiling






✤ Single impact on the front or rear of the chamber's ceiling




























THE UNIVERSITY of EDINBURGH School of Engineering

Repair was Cerding

• Impalsiveloads *Impattoads





Acknowledgement

- The first author would like to thank the Indonesian Endowment Fund for Education (LPDP)
- the European Community's Seventh Framework Progamme through the Integrity Activity HYDRALAB IV, Contract no 261520 for the access to the testing facility
- Jon Alderson (HR Wallingford), Viviano Russo (Queen's University of Belfast), Vincenzo Ferrante (Second University of Naples), Stefan Schimmel and Matthias Kudella (GWK) and the support team at the GWK for design, construction, and testing of these experiments

Conclusions

- Wave conditions under which sloshing is more likely to occur have been characterised for no sloshing, low sloshing, medium sloshing, and impact sloshing.
- Three types of in-chamber ceiling impact have been characterised and quantified: single impact, successional impact, and whole water column impact
- Impact pressures of up to **12 pgH** have been measured within chamber
- Further comparison between the front wall and the in-chamber ceiling proves that the ceiling impact is at least comparable with the front wall
- Some degree of sloshing is not uncommon in an OWC chamber during operation, so it should be part of the design consideration

